

Report No.: FR830505A

Appendix D. Setup Photographs

<Conducted Emission>






Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : D1 of D2
Report Issued Date Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0




<Radiated Emission>

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : D2 of D2
Report Issued Date Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR830505A