
3. Internal Photograph of EUT

Brand Name: PAX; Model Name: D200;

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 12 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602



TEL: 86-755- 3320-2398 FCC ID: V5PD200W


Page Number : 13 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01



Report No.: EP391602



TEL: 86-755-3320-2398 FCC ID: V5PD200W

Page Number : 14 of 38 Report Issued Date: Nov. 20, 2013 Report Version : Rev. 01



Report No.: EP391602



TEL: 86-755-3320-2398 FCC ID: V5PD200W

Page Number : 15 of 38 Report Issued Date: Nov. 20, 2013 Report Version : Rev. 01




Report No.: EP391602



TEL: 86-755-3320-2398 FCC ID: V5PD200W

Page Number : 16 of 38 Report Issued Date: Nov. 20, 2013 Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: V5PD200W Page Number : 17 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01


Report No.: EP391602



TEL: 86-755-3320-2398 FCC ID: V5PD200W

Page Number : 18 of 38 Report Issued Date: Nov. 20, 2013 Report Version : Rev. 01

Report No.: EP391602



TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 19 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W Page Number : 20 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602



TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 21 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602



TEL: 86-755- 3320-2398 FCC ID: V5PD200W


Page Number : 22 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01



Report No.: EP391602



TEL: 86-755-3320-2398 FCC ID: V5PD200W

Page Number : 23 of 38 Report Issued Date: Nov. 20, 2013 Report Version : Rev. 01

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 24 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 25 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 26 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 27 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 28 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 29 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01





TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 30 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602



TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 31 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602



TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 32 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01




Report No.: EP391602



TEL: 86-755-3320-2398 FCC ID: V5PD200W

: 33 of 38 Page Number Report Issued Date: Nov. 20, 2013 Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 34 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 35 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01

Report No.: EP391602




TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 36 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 37 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01





TEL: 86-755- 3320-2398 FCC ID: V5PD200W

Page Number : 38 of 38

Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01