

Report No.: FR632806

Appendix A. Setup Photographs

<Conducted Emission>




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX5RF Page Number : A1 of A2
Report Issued Date : May 13, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0




Report No.: FR632806

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX5RF Page Number : A2 of A2
Report Issued Date : May 13, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0