

Appendix B. Setup Photographs

<Conducted Emission>





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : B1 of B2
Report Issued Date Aug. 24, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR771112A






<Radiated Emission> Z Plane LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : B2 of B2
Report Issued Date Aug. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR771112A