
Appendix E. Setup Photographs

<Conducted Emission>






TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2APJ4-SLM757A Page Number : E1 of E2
Report Issued Date : Nov. 29, 2018
Report Version : Rev. 01

Report No.: FR891203D


Report Template No.: BU5-FR15EWL AC MA Version 2.0

<Radiated Emission>

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2APJ4-SLM757A Page Number : E2 of E2
Report Issued Date : Nov. 29, 2018
Report Version : Rev. 01

Report No.: FR891203D

Report Template No.: BU5-FR15EWL AC MA Version 2.0