2. Internal Photograph of EUT

Brand Name: PAX; Model Name: SP20

Report No.: EP370304



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 7 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01

Report No.: EP370304



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 8 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01

Report No.: EP370304



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 9 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01


Report No.: EP370304



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 10 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01

Report No.: EP370304



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 11 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01


Report No.: EP370304



TEL: 86-755-3320-2398 FCC ID: V5PSP20

: 12 of 18 Page Number Report Issued Date : Jul. 26, 2013 Report Version : Rev. 01

Report No.: EP370304




TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 13 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01

Report No.: EP370304


Brand Name: PAX; Model Name: SP20



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 14 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01


Report No.: EP370304



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 15 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01


Report No.: EP370304



TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 16 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01

Report No.: EP370304




TEL: 86-755- 3320-2398 FCC ID: V5PSP20

Page Number : 17 of 18
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01



Report No.: EP370304



TEL: 86-755-3320-2398 FCC ID: V5PSP20

Page Number : 18 of 18 Report Issued Date : Jul. 26, 2013 Report Version : Rev. 01