


Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : D1 of D2
Report Issued Date Jan. 25, 2018
Report Version : Rev. 01


Report No.: FR811505B

Report Template No.: BU5-FR15CBT4.0 Version 2.0




Report No. : FR811505B

<Radiated Emission>



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : D2 of D2
Report Issued Date Jan. 25, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0