
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for LTE Band 2

LF



HF




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : C1 of C5
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Z Plane for LTE Band 4

LF



HF




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : C2 of C5
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Z Plane for LTE Band 5/17

LF



HF




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : C3 of C5
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Y Plane for LTE Band 12

LF




HF




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : C4 of C5
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Z Plane for LTE Band 13

LF



HF



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : C5 of C5
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0