

Report No. : FR6N0307D

Appendix D. Setup Photographs

<Conducted Emission>




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD200V4 Page Number : D1 of D2
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.2




Report No.: FR6N0307D

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD200V4 Page Number : D2 of D2
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.2