# Appendix C. Setup Photographs


## <Radiated Emission>

Z Plane for 22H

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C1 of C3
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 2.0

Report No. : FG862615A


## Report No.: FG862615A

### Y Plane for 24E

LF



HF




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C2 of C3
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01


Report Template No.: BU5-FG22/24/27 Version 2.0

### Y Plane for 27L

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C3 of C3
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No. : FG862615A

Report Template No.: BU5-FG22/24/27 Version 2.0