

## Appendix B. Setup Photographs

## <Conducted Emission>

## Mode 1




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: V5PD900W Page Number : B1 of B2
Report Issued Date : Jul. 24, 2012
Report Version : Rev. 01


Report No.: FR242415B



## <Radiated Emission>



Low Frequency



High Frequency

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: V5PD900W Page Number : B2 of B2
Report Issued Date : Jul. 24, 2012
Report Version : Rev. 01

Report No.: FR242415B