
3. Internal Photograph of EUT

Brand Name: PAX; Model Name: D180


Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 11 of 38
Report Issued Date : Dec. 08, 2015



Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

: 12 of 38 Page Number Report Issued Date : Dec. 08, 2015



Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

: 13 of 38 Page Number Report Issued Date : Dec. 08, 2015 Report Version : Rev. 01




Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

: 14 of 38 Page Number Report Issued Date : Dec. 08, 2015 Report Version : Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 15 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01



Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

: 16 of 38 Page Number Report Issued Date : Dec. 08, 2015



Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 17 of 38 Report Issued Date : Dec. 08, 2015 Report Version : Rev. 01



Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 18 of 38 Report Issued Date : Dec. 08, 2015 Report Version : Rev. 01



Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 19 of 38 Report Issued Date : Dec. 08, 2015 Report Version : Rev. 01




Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 20 of 38 Report Issued Date : Dec. 08, 2015


Report No.: EP5N1110





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 21 of 38 Report Issued Date : Dec. 08, 2015 Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 22 of 38 Report Issued Date : Dec. 08, 2015


Report No.: EP5N1110

Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 23 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01


Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 24 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01




Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 25 of 38 Report Issued Date : Dec. 08, 2015 Report Version : Rev. 01


Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 26 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01



Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 27 of 38

Report Issued Date : Dec. 08, 2015


Report Version : Rev. 01

Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 28 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01

Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 29 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01

Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 30 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01

Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 31 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01

Report No.: EP5N1110




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 32 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01

Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 33 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01


Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 34 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01

Report No.: EP5N1110


Brand Name: PAX; Model Name: D180



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 35 of 38
Report Issued Date : Dec. 08, 2015
Report Version : Rev. 01



Report No.: EP5N1110



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 36 of 38 Report Issued Date : Dec. 08, 2015

09

30

Brand Name: PAX; Model Name: D180 30 50 0,8

08


Report No.: EP5N1110

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF

Page Number : 37 of 38 Report Issued Date : Dec. 08, 2015





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD180SRF Page Number : 38 of 38
Report Issued Date : Dec. 08, 2015