

Report No.: FR5D2302D

Appendix D. Setup Photographs

<Conducted Emission>




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : D1 of D2
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01



<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : D2 of D2
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2302D