## Appendix C. Setup Photographs


<Radiated Emission>

X Plane for LTE Band 2

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA920-LTE Page Number : C1 of C4
Report Issued Date : Dec. 25, 2017
Report Version : Rev. 01

Report No.: FG7N0804B

Report Template No.: BU5-FGLTE Version 1.6

## X Plane for LTE Band 4 / 12

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA920-LTE Page Number : C2 of C4
Report Issued Date : Dec. 25, 2017

Report No.: FG7N0804B

Report Version : Rev. 01


Report Template No.: BU5-FGLTE Version 1.6

## Z Plane for LTE Band 5 / 17

LF



HF



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA920-LTE Page Number : C3 of C4
Report Issued Date : Dec. 25, 2017

Report No.: FG7N0804B


Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

## X Plane for LTE Band 13

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA920-LTE Page Number : C4 of C4
Report Issued Date : Dec. 25, 2017

Report No.: FG7N0804B

Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6