

Report No. : FA391602

## Appendix D. Test Setup Photos





Front of the DUT with Phantom 0cm Gap

Back of the DUT with Phantom 0cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD200W Page Number : D1 of D1
Report Issued Date : Nov. 20, 2013

Report Version : Rev. 01