# Appendix C. Setup Photographs


## <Radiated Emission>

X Plane with Accessories for LTE Band 4 / 13 / 17

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PAR8 Page Number : C1 of C4
Report Issued Date : Apr. 09, 2019
Report Version : Rev. 01

Report No.: FG8D0615B


Report Template No.: BU5-FGLTE Version 2.0

## X Plane for LTE Band 2

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PAR8 Page Number : C2 of C4
Report Issued Date : Apr. 09, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG8D0615B

#### LTE Band 5 with Cradle 2

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PAR8 Page Number : C3 of C4
Report Issued Date : Apr. 09, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0


Report No. : FG8D0615B

## Y Plane with Accessories for LTE Band 12

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PAR8 Page Number : C4 of C4
Report Issued Date : Apr. 09, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0

Report No. : FG8D0615B