Appendix C. Setup Photographs


<Radiated Emission>

Z Plane for Part 22H

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : C1 of C3
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report No. : FG771112A


Report Template No.: BU5-FG22/24/27 Version 1.2

X Plane for Part 24E

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : C2 of C3
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report No. : FG771112A


Report Template No.: BU5-FG22/24/27 Version 1.2

Z Plane for Part 27L

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : C3 of C3
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report No. : FG771112A

Report Template No.: BU5-FG22/24/27 Version 1.2