


Appendix D. Setup Photographs

<Conducted Emission>

Mode 2





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number D1 of D2
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report No.: FR811505C


Report Template No.: BU5-FR15CWL Version 2.0




<Radiated Emission>

Y Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number D2 of D2
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0

Report No.: FR811505C