

Report No.: FR632903D

Appendix D. Setup Photographs


<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX5BW Page Number : D1 of D2
Report Issued Date : Jul. 25, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0




<Radiated Emission>



Report No.: FR632903D

From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX5BW Page Number : D2 of D2
Report Issued Date : Jul. 25, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0