

Report No. : FR942424D

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



Remote View



Rear View

Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PA910 Page Number : D1 of D2
Report Issued Date : Jun. 19, 2019
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL AC MA Version 2.0



Report No.: FR942424D

<Radiated Emission>

from 9 kHz to 30 MHz



from 30MHz to 1GHz



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PA910 Page Number : D2 of D2
Report Issued Date : Jun. 18, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 2.0