


## Report No.: FR6N0307C

## Appendix D. Setup Photographs

## <Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD200V4

Page Number : D1 of D2 Report Issued Date : Dec. 08, 2016 Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3







## <Radiated Emission>

**Z** Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PD200V4 Page Number : D2 of D2
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR6N0307C