Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for LTE Band 2

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C1 of C5
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG862615B

Y Plane for LTE Band 4

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C2 of C5
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No. : FG862615B

X Plane for LTE Band 5

LF



HF



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C3 of C5
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Report No. : FG862615B


Report No. : FG862615B

Y Plane for LTE Band 12, Band 13

LF



HF



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C4 of C5
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Z Plane for LTE Band 17

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : C5 of C5
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Report No. : FG862615B