

Report No.: FR632903A

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX5BW

Page Number : B1 of B2 Report Issued Date: Jul. 25, 2016

Report Version : Rev. 01




Report No.: FR632903A


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX5BW Page Number : B2 of B2
Report Issued Date : Jul. 25, 2016
Report Version : Rev. 01