

Report No.: FR8O2912D

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PE600 Page Number : D1 of D2
Report Issued Date : Dec. 27, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0



Report No.: FR8O2912D

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PE600 Page Number : D2 of D2
Report Issued Date : Dec. 27, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0