


#### Report No. : FR611521

# Appendix D. Setup Photographs

## <Conducted Emission>




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS300 Page Number : D1 of D2
Report Issued Date : Mar. 17, 2016
Report Version : Rev. 01




#### **Report No. : FR611521**

## <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS300 Page Number : D2 of D2
Report Issued Date : Mar. 17, 2016
Report Version : Rev. 01