2. Internal Photograph of EUT

Brand Name: PAX / Model Name: IM300 / Marketing Name: IM300

Report No.: EP811505



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 8 of 29

Report Issued Date : Jan. 25, 2018 Report Version : Rev. 01


Report No.: EP811505




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 9 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report No.: EP811505





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 10 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 11 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01






TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW

Page Number : 12 of 29 Report Issued Date : Jan. 25, 2018

Report Version : Rev. 01



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 13 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01



Brand Name: PAX / Model Name: IM300 / Marketing Name: IM300 8 9 00 00 L ot 20 to

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW

Page Number : 14 of 29 Report Issued Date : Jan. 25, 2018

Report No.: EP811505

Report Version : Rev. 01







TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 15 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report No.: EP811505



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 16 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 17 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 18 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report No.: EP811505


Brand Name: PAX / Model Name: IM300 / Marketing Name:


Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 19 of 29


Report No.: EP811505

Report Issued Date : Jan. 25, 2018 Report Version : Rev. 01





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 20 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 21 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report No.: EP811505



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 22 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 23 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 24 of 29
Report Issued Date : Jan. 25, 2018

Report No.: EP811505

Report Version : Rev. 01



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 25 of 29
Report Issued Date : Jan. 25, 2018

Report No.: EP811505

Report Version : Rev. 01



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 26 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report No.: EP811505

Report No.: EP811505



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 27 of 29
Report Issued Date : Jan. 25, 2018

Report Version : Rev. 01

Report No.: EP811505



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 28 of 29
Report Issued Date : Jan. 25, 2018

Report Version : Rev. 01

Report No.: EP811505



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : 29 of 29
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01