
3. Internal Photograph of EUT

Brand Name: PAX; Model Name: \$900

Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 14 of 40 Report Issued Date : Jun. 19, 2015

Report Version : Rev. 01




Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900


Page Number : 15 of 40 Report Issued Date : Jun. 19, 2015 : Rev. 01 Report Version

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 16 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01


Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 17 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01


Report No.: EP542304

Brand Name: PAX; Model Name: S900




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 18 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 19 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 20 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 21 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01



Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 22 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01



Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 23 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01



Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

: 24 of 40 Page Number Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01


Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 25 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01




Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900


Page Number : 26 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 27 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01


Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 28 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01



Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 29 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01




Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900


: 30 of 40 Page Number Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01

Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 31 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 32 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 33 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01


Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 34 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01



Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 35 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01

Report No.: EP542304

Brand Name: PAX; Model Name: S900




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 36 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 37 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 38 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01

Report No.: EP542304



Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 39 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01

Report No.: EP542304

Brand Name: PAX; Model Name: \$900



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 40 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01