

Report No.: FR830505D

## **Appendix D. Setup Photographs**

## <Conducted Emission>






Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA60 Page Number : D1 of D2
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0



## <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595

FCC ID: V5PA60 Report Template No.: BU5-FR15CNFC Version 2.0

Page Number : D2 of D2

Report No.: FR830505D

Report Issued Date : Jun. 12, 2018 Report Version : Rev. 01