

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : D1 of D2
Report Issued Date Aug. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0


Report No.: FR771112B



<Radiated Emission> Z Plane LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : D2 of D2
Report Issued Date Aug. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0

Report No.: FR771112B