

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PAR8 Page Number : D1 of D2
Report Issued Date : Apr. 09, 2019
Report Version : Rev. 01

Report No.: FR8D0615D

Report Template No.: BU5-FR15CNFC Version 2.0



Report No.: FR8D0615D

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PAR8 Page Number : D2 of D2
Report Issued Date : Apr. 09, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 2.0