Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-86379589 FAX: +86-755-86379595 FCC ID: V5PA910

Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0

Report Issued Date : Jun. 19, 2019

: E1 of E2


Page Number

Report No.: FR942424B

<Radiated Emission>

X Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-86379589 FAX: +86-755-86379595 FCC ID: V5PA910 Page Number : E2 of E2
Report Issued Date : Jun. 19, 2019
Report Version : Rev. 01

Report No.: FR942424B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0