

## st Report No. : FR670104D

## Appendix D. Setup Photographs


## <Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PQ80 Page Number : D1 of D2
Report Issued Date : Aug. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0




## <Radiated Emission>



Report No.: FR670104D

From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PQ80 Page Number : D2 of D2
Report Issued Date : Aug. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0