
Appendix A. Setup Photographs

<Conducted Emission>

Mode 4





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : A1 of A2
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3

Report No. : FC811505


<Radiated Emission>

Mode 6

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PIM300BW Page Number : A2 of A2
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report No. : FC811505

Report Template No.: BU5-FD15B Version 1.3