

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : E1 of E2
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: FR862615B

Report Template No.: BU5-FR15CBT4.0 Version 2.0



<Radiated Emission>

Z Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : E2 of E2
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: FR862615B

Report Template No.: BU5-FR15CBT4.0 Version 2.0