
Report No.: EP5D2302



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 27 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01




Report No.: EP5D2302



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE


: 28 of 45 Page Number Report Issued Date : Jan. 21, 2016 Report Version : Rev. 01

Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 29 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 30 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 31 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 32 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 33 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 34 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 35 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 36 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 37 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 38 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: EP5D2302



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 39 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01


Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 40 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01



Report No.: EP5D2302




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 41 of 45 Report Issued Date : Jan. 21, 2016 Report Version : Rev. 01



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 42 of 45 Report Issued Date : Jan. 21, 2016 Report Version : Rev. 01

Report No.: EP5D2302




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 43 of 45 Report Issued Date : Jan. 21, 2016 Report Version : Rev. 01

Report No.: EP5D2302

Report No.: EP5D2302




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 44 of 45
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01



Report No.: EP5D2302



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS920FDD-LTE Page Number : 45 of 45 Report Issued Date : Jan. 21, 2016 Report Version : Rev. 01