


Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PE600 Page Number : E1 of E2
Report Issued Date : Dec. 27, 2018
Report Version : Rev.01

Report Template No.: BU5-FR15EWL AC MA Version 2.0




<Radiated Emission>

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PE600 Page Number : E2 of E2
Report Issued Date : Dec. 27, 2018
Report Version : Rev.01

Report Template No.: BU5-FR15EWLAC MA Version 2.0