3. Internal Photograph of EUT

Brand Name: PAX / Model Name: A930 / Marketing Name: A930

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 14 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 15 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 16 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 17 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 18 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 19 of 38

Report Issued Date : Aug. 17, 2018


Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 20 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 21 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 22 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 23 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 24 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 25 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930

: 26 of 38 Page Number Report Issued Date : Aug. 17, 2018 Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 27 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 28 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 29 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 30 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 31 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 32 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 33 of 38
Report Issued Date : Aug. 17, 2018
Report Version : Rev. 01

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 34 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930

Page Number : 35 of 38 Report Issued Date : Aug. 17, 2018 : Rev. 01

Report Version

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 36 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 37 of 38
Report Issued Date : Aug. 17, 2018

Report No.: EP862615



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5PA930 Page Number : 38 of 38
Report Issued Date : Aug. 17, 2018