

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-755- 3320-2398 FCC ID: V5PD210BT Page Number : B1 of B2 Report Issued Date : May 03, 2013

Report No.: FR330704A


Report Version : Rev. 01



<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: V5PD210BT Page Number : B2 of B2
Report Issued Date : May 03, 2013
Report Version : Rev. 01

Report No.: FR330704A