Appendix C. Setup Photographs


<Radiated Emission>

X Plane for LTE Band 4

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : C1 of C4
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.6


Report No.: FG771112B

Y Plane for LTE Band 5

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : C2 of C4
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.6


Report No. : FG771112B

Z Plane for LTE Band 2

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : C3 of C4
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.6


Report No. : FG771112B

Y Plane for LTE Band 17

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : C4 of C4
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.6

Report No. : FG771112B