

Report No. : FR330801

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: V5PS90WCDMA Page Number : B1 of B2
Report Issued Date : Apr. 26, 2013
Report Version : Rev. 01



Report No. : FR330801

<Radiated Emission>

9KHz~30MHz



30MHz~1GHz



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: V5PS90WCDMA Page Number : B2 of B2
Report Issued Date : Apr. 26, 2013
Report Version : Rev. 01