1. External Photograph of EUT

Brand Name: PAX; Model Name: \$900

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 1 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01




Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 2 of 40 Report Issued Date : Jun. 19, 2015

Report Version : Rev. 01





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 3 of 40 Report Issued Date : Jun. 19, 2015

: Rev. 01

Report Version

Report No.: EP542304

Brand Name: PAX; Model Name: \$900



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 4 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304

Brand Name: PAX; Model Name: \$900




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 5 of 40

Report Issued Date : Jun. 19, 2015

Report Version : Rev. 01

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 6 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 7 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 8 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

2. **Photograph of Accessory**

Brand Name: PAX; Model Name: S900

Report No.: EP542304

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	HuntKey
	Model Name	HKA00909010-8F
Battery	Brand Name	PAX
	Model Name	IS135
AC Cable	Signal Line Type	1.8m, shielded cable, without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 9 of 40 Report Issued Date : Jun. 19, 2015

Report Version : Rev. 01

Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 10 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900 Page Number : 11 of 40
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No.: EP542304




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 12 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01



Report No.: EP542304



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PS900

Page Number : 13 of 40 Report Issued Date : Jun. 19, 2015 Report Version : Rev. 01