

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : D1 of D2
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01


Report No.: FR771112C

Report Template No.: BU5-FR15CWL Version 2.0




<Radiated Emission>

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: V5P-D2204GBW Page Number : D2 of D2
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01

Report No.: FR771112C

Report Template No.: BU5-FR15CWL Version 2.0