Appendix C. Setup Photographs


<Radiated Emission>

For 22H

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PA920-2019 Page Number : C1 of C2
Report Issued Date : Apr. 09, 2019
Report Version : Rev.01

Report No. : FG8D0615A


Report Template No.: BU5-FG22/24/27 Version 2.0

For 24E, 27L

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PA920-2019 Page Number : C2 of C2
Report Issued Date : Apr. 09, 2019
Report Version : Rev.01

Report No.: FG8D0615A

Report Template No.: BU5-FG22/24/27 Version 2.0