## Appendix E. Setup Photographs

## <Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5P-D2204GMV Page Number : E1 of E2
Report Issued Date Dec. 10, 2018
Report Version : Rev. 01

Report No.: FR882809C

Report Template No.: BU5-FR15CWL AC MA Version 2.0


## <Radiated Emission>

## **Z** Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5P-D2204GMV Page Number : E2 of E2
Report Issued Date Dec. 10, 2018
Report Version : Rev. 01

Report No.: FR882809C

Report Template No.: BU5-FR15CWL AC MA Version 2.0