

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch 香港商立德國際商品試驗有限公司 桃園分公司

No. 19, Hwa Ya 2nd Rd., Wen Hwa Tsuen, Kwei Shan Hsiang, Taoyuan Hsien 33383, Taiwan

TEL: 886-3-3183232 FAX: 886-3-3270892

http://www.adt.com.tw/E-mail: service@mail.adt.com.tw

Date: October 31, 2014

SUBJECT: Supersede for FCC ID: V65E4520, Granted Date: 10/28/2014

To Whom It May Concern:

We, **Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch.**, hereby declare on our client's behalf that the original submitted SAR test report and Tune-up Procedure should be superseded due to some typo of the tune-up tolerance on GSM 1900(EDGE). The superseded documents are listed as below:

| Original File name | Newly File name |
|------------------------------------|------------------------------------|
| V65E4520_test rpt_RF Exposure Info | V65E4520_test rpt_RF Exposure Info |
| (SAR).PDF | (SAR)_R1.PDF |
| V65E4520_tech_Tune up | V65E4520_tech_Tune up |
| Procedure.PDF | Procedure_R1.PDF |

Except for the change above, no other modification is performed. Also, the change does not have any impact on the approved radio parameter such as power, frequency range, modulation etc.

Should you have any question or comment regarding this matter, please do not hesitate to contact me.

Sincerely yours,

Daniel Lee / Vice President

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-318 3232 ext. 1857

Fax: 886-3-318 5050



Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch 香港商立德國際商品試驗有限公司 桃園分公司

No. 19, Hwa Ya 2nd Rd., Wen Hwa Tsuen, Kwei Shan Hsiang, Taoyuan Hsien 33383, Taiwan

TEL: 886-3-3183232 FAX: 886-3-3270892

http://www.adt.com.tw / E-mail: service@mail.adt.com.tw