

3731 Rutledge Road Albuquerque, NM 87109 505-856-5285 phone 505-856-5942 fax

Monitron Label Placement July 18, 2008

FLOM TEST LABS 3356 N San Marcos Suite 107 Chandler AZ, 85225

Dear Jackie Pillai:

Because Monitron Host systems are buried, the FCC Label for the module will be placed inside the lid of the host products to prevent any degradation to the label. These units are typically buried for several years and there is a concern that the label may not be readable when the unit is uncovered. However, with the label located inside the lid, the label will be visible when the unit is serviced.

Best Regards,

Max A. Lopez

Engineer Supervisor

Ext. 112