

3731 Rutledge Road Albuquerque, NM 87109 505-856-5285 phone 505-856-5942 fax

Subject: Tune Up Procedure for Monitron Transmitter

Date: June 20, 2008

RE: FCC ID: V88-TRX777

Gentlemen,

This letter is to state that there is not a Tuning Procedure which needs to be completed by the customer. The setup for the radio is software controlled and is completed at the factory during the manufacturing process for the transmitter. The customer does have the ability to set the frequency depending on the location the final product is being used. If there is additional information needed, please let me know.

Sincerely, Monitron, Inc.

Max A. Lopez

Engineer Supervisor