

3731 Rutledge Road Albuquerque, NM 87109 505-856-5285 phone 505-856-5942 fax

John Erhard, Engineering Manager Compliance Testing LLC dba Flom Test Lab

January 11, 2010

REF.: Monitron inc. FCC ID V88-TRX876 Subject: Shielding of Transmitter, L5L module

John,

The Transmitter, L5L module, is sandwiched between two ground planes. This is true in every application the module is to be used in. Please let me know if further information is required.

Sincerely, Monitron, Inc.

Max A. Lopez President