




**Appendix A. Test Photos** 

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Report No.: FR681919ZW



## FCC Test Report

Report No. : FR681919ZW




Side view

TEL: 886-3-327-3456 FAX: 886-3-327-0973




FCC Test Report Report No.: FR681919ZW

## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions below 1G



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973




FCC Test Report

Report No. : FR681919ZW

## For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973