
## **INTERTEK TESTING SERVICE**


Report No.: 15061175HKG-001

## **Equipment Photographs**

Model: 94146

(External)





FCC ID: V9Q-94146F27